

Service Bulletin

Maintenance of Way Equipment

Date: 10.16.2026

RRP Service Bulletin No: RRP SB410

Title: Left and Right Outer Jack Tubes updated with additional reinforcement

Rating:

ALERT

(Potential Problem)


INFORMATION

(Action Is Optional)


DIRECTIVE

(Action Is Required)


PRODUCT IMPROVEMENT

(Enhance Product)

Product Series: Advance Tie Plate Inserter [ATPI]

Serial No: See Below

BNSF

ATPI-014	932574	BNSF	X3800191
ATPI-014	793082	BNSF	X3800191
ATPI-015	932574	BNSF	X3800192
ATPI-016	932574	BNSF	X3800193
ATPI-017	932574	BNSF	X3800194

APTI-045	932587	BNSF	X3800196
APTI-046	932587	BNSF	X3800197
APTI-047	932587	BNSF	X3800198
APTI-048	932587	BNSF	X3800199
APTI-049	932587	BNSF	X3800200
APTI-050	932587	BNSF	X3800195

ATPI-063	932587	BNSF	X3800205
ATPI-064	932587	BNSF	X3800206
ATPI-065	932587	BNSF	X3800207
ATPI-066	932587	BNSF	X3800208

ATPI-079	932602	BNSF	X3800213
ATPI-080	932602	BNSF	X3800214
ATPI-081	932602	BNSF	X3800215
ATPI-082	932602	BNSF	X3800216
ATPI-083	932602	BNSF	X3800217
ATPI-084	932602	BNSF	X3800218

ATPI-070	932587	BNSF	X3800209
ATPI-071	932587	BNSF	X3800210

CN

ATPI-009	935574	CN	438-61
ATPI-010	935574	CN	438-62

ATPI-019	935588	CN-W	CN43865
ATPI-020	935588	CN-W	CN43866
ATPI-021	945588	CN-S	CN43863
ATPI-022	945588	CN-S	CN43864

ATPI-030	935588	CN-W	CN43867
ATPI-031	935588	CN-W	CN43868

APTI-042	935588	CN	CN43869
ATPI-043	935588	CN	CN43870

APTI-051	945588	CN-S	CN43871
APTI-052	945588	CN-S	CN43872

CPKC

ATPI-008	933574	CP	5014-19
ATPI-027/036	933588	CP	5014.21
APTI-028/037	933588	CP	5014-22

ATPI-029/038	933588	CP	5014-23
APTI-032	933588	CP	7014-14
ATPI-033/035	933588	CP	5014-20

RELAM

ATPI-001-16	915575	RELAM	
ATPI-018	930587	RELAM	X3800202

ATPI-034	932587	RELAM	X3800203
ATPI-041	932587	RELAM	X3800204
APTI-044	932587	RELAM	X3800201

UPRR

ATPI-002-17	915574	UPRR	RLPI-1701
ATPI-003-17	915574	UPRR	RLPI-1702
ATPI-004-17	915574	UPRR	RLPI-1703
ATPI-005-17	915574	UPRR	RLPI-1704
ATPI-006-17	915574	UPRR	RLPI-1705
ATPI-007-17	915574	UPRR	RLPI-1706

ATPI-011	915574	UPRR	RLPI-1801
ATPI-012	915574	UPRR	RLPI-1802
ATPI-013	915574	UPRR	RLPI-1803

ATPI-023	931588	UPRR	RLPI-1901
ATPI-024	931588	UPRR	RLPI-1902
ATPI-025	931588	UPRR	RLPI-1903
ATPI-026	931588	UPRR	RLPI-1904


ATPI-056	931588	UPRR	RLPII-2104
ATPI-057	931588	UPRR	RLPI-2105
ATPI-058	931588	UPRR	RLPI-2106
ATPI-059	931588	UPRR	RLPI-2107
ATPI-060	931588	UPRR	RLPI-2108
ATPI-061	931588	UPRR	RLPI-2201
APTI-062	931588	UPRR	RLPI-2202

APTI-053	931588	UPRR	RLPI-2101
APTI-054	931588	UPRR	RLPI-2102
APTI-055	931588	UPRR	RLPI-2103

ATPI-067	931587	UPRR	RLPI-2301
ATPI-068	931587	UPRR	RLPI-2302
ATPI-069	931587	UPRR	RLPI-2401
ATPI-072	931587	UPRR	RLPI-2402
ATPI-073	931587	UPRR	RLPI-2403
ATPI-074	931587	UPRR	RLPI-2404

ATPI-075	931587	UPRR	RLPI-2405
ATPI-076	931587	UPRR	RLPI-2406
ATPI-077	931587	UPRR	RLPI-2407
ATPI-078	931587	UPRR	RLPI-2408
ATPI-085	931587	UPRR	RLPI-2601
ATPI-086	931587	UPRR	RLPL-2602

Summary: Outer Jack Tubes: Left **RRP# 780865** & Right **RRP# 780866** have been updated to Rev. 4 with additional reinforcements to prevent possible breakage.



Action: Check the left and right Outer Jack Tubes for damage (cracking / fatigue). If necessary, replace the old outer jack tubes with the updated version, Rev. 4: Left **RRP# 780865** & Right **RRP# 780866**.

Completion / Resolution: Continue normal operation after inspecting or replacing the outer jack tubes.

Contact: If you have any questions or we can be of any service, please contact the Racine Railroad Products Service Department at (262)-637-9681 or fieldservice@racinerailroad.com.