

Service Bulletin

Maintenance of Way Equipment

Date: 9.29.2026**RRP Service Bulletin No:** RRP SB407**Title:** AM3 Swingarm Cylinder Pin**Rating:****ALERT**

(Potential Problem)

**INFORMATION**

(Action Is Optional)

**DIRECTIVE**

(Action Is Required)

**PRODUCT IMPROVEMENT**

(Enhance Product)

Product Series: Anchor Applicator 3 (AM3)**Serial No:**

AM3-012	931589	CN
---------	--------	----

AM3-022	793179	CN
---------	--------	----

AM3-008	793224	CSX
AM3-009	793224	CSX
AM3-010	793224	CSX
AM3-011	793224	CSX
AM3-017	793224	CSX

AM3-018	793224	CSX
AM3-019	793224	CSX
AM3-020	793224	CSX
AM3-021	793224	CSX

AM3-001	930589	UPRR	AAA-2407
AM3-002	931589	UPRR	AAA-2401
AM3-003	931589	UPRR	AAA-2402
AM3-004	931589	UPRR	AAA-2003
AM3-005	931589	UPRR	AAA-2404
AM3-006	931589	UPRR	AAA-2405

AM3-007	931589	UPRR	AAA-2406
AM3-013	931589	UPRR	AAA-2501
AM3-014	931589	UPRR	AAA-2502
AM3-015	931589	UPRR	AAA-2503
AM3-016	931589	UPRR	AAA-2504

Summary: AM3 Swingarm Cylinder RRP# 471023, Hydraulic Cylinder needs to be replaced with RRP# 721533 Apply Cylinder Assembly to improve the cylinder pin life.

Action: Exchange any new/unused spare RRP# 471023 cylinder for the new updated RRP# 721533 cylinder assembly.

Please contact RRP Customer Service [(262)-637-9681 or custserv@racinerailroad.com.] to return the RRP# 471023 cylinder and send the RRP# 721533 replacement.

Completion / Resolution: Continue with normal machine operation after replacing the cylinder assembly.