

Service Bulletin

Maintenance of Way Equipment

Date: 02.07.2025

RRP Service Bulletin No: RRP SB395

Title: Anchormatic 3 (AM3) Work Arm Lock

Rating:



ALERT
(Potential Problem)



INFORMATION
(Action Is Optional)



DIRECTIVE
(Action Is Required)



PRODUCT IMPROVEMENT
(Enhance Product)

Product Series: Anchormatic 3

Serial No:

AM3-001	UPRR	AAA-2407
AM3-002	UPRR	AAA-2401
AM3-003	UPRR	AAA-2402
AM3-004	UPRR	AAA-2003

AM3-005	UPRR	AAA-2404
AM3-006	UPRR	AAA-2405
AM3-007	UPRR	AAA-2406

Summary:

Machines have experienced workarm locks stuck in the unlocked position. This can lead to the workarms falling during track travel potentially damaging the machine.

Action:

RRP is currently working on both software protections and an improved lock design. The updated software is version 6.1.10.

Resolution:

Operators must verify, by visual inspection, that the swing arm locks are engaged correctly before track traveling and when switching from work to travel mode.

