

Service Bulletin

Maintenance of Way Equipment

Date: 8.05.2026**RRP Service Bulletin No:** RRP SB405**Title:** AM3 Apply Plate/Plunger Improvement**Rating:****ALERT**

(Potential Problem)

**INFORMATION**

(Action Is Optional)

**DIRECTIVE**

(Action Is Required)

**PRODUCT IMPROVEMENT**

(Enhance Product)

Product Series: Anchor Applicator 3 (AM3)**Serial No:**

AM3-001	930589	UPRR	AAA-2407
AM3-002	931589	UPRR	AAA-2401
AM3-003	931589	UPRR	AAA-2402
AM3-004	931589	UPRR	AAA-2003
AM3-005	931589	UPRR	AAA-2404
AM3-006	931589	UPRR	AAA-2405
AM3-007	931589	UPRR	AAA-2406
AM3-013	931589	UPRR	AAA-2501
AM3-014	931589	UPRR	AAA-2502
AM3-015	931589	UPRR	AAA-2503
AM3-016	931589	UPRR	AAA-2504

AM3-008	CSX
AM3-009	CSX
AM3-010	CSX
AM3-011	CSX
AM3-017	CSX
AM3-018	CSX
AM3-019	CSX
AM3-020	CSX
AM3-021	CSX

AM3-012	931589	CN
AM3-022	793179	CN

Summary: The latch plunger has been replaced with a longer assembly that will not fit the older apply plates. This has been done to improve plunger/anchor latch life.

All new apply plates ordered **after May2026** will be made to fit the improved Gen2 plunger.

Any apply plate originally equipped or purchased **before May2026** will require the Gen1 plunger assembly. The Gen1 plunger has been assigned a **new part number 721713**.

Apply Plate Assembly part numbers are listed on page 2.

Apply Plate Assembly Part Numbers:

Fair	Left 719854	Right 719853
Unit5	Left 720199	Right 720198
Viper	Left 719768	Right 719766
Unit Spring	Left 720458	Right 720457
Plunger Gen1	721713	
Plunger Gen2	721294	

Action: Review the following Apply Plate Assembly part numbers to make sure you are ordering the correct parts as needed.

Completion / Resolution: Continue with normal machine operation after replacing the necessary parts for the plate assembly.

Contact: If you have any questions or we can be of any service, please contact the Racine Railroad Products Service Department at (262)-637-9681 or fieldservice@racinerailroad.com.